UNCLASSIFIED

AD NUMBER AD128187 CLASSIFICATION CHANGES TO: UNCLASSIFIED FROM: CONFIDENTIAL LIMITATION CHANGES

TO:

Approved for public release; distribution is unlimited.

FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors;

Administrative/Operational Use; NOV 1956. Other requests shall be referred to Department of the Army, Aberdeen Proving Ground, MD.

AUTHORITY

APG ltr 19 Nov 1980 ; APG ltr 19 Nov 1980

UNCLASSIFIED

AD 128/87

CLASSIFICATION CHANGED

TO: UNCLASSIFIED_

FROM: CONFIDENTIAL

AUTHORITY:

= APG PA 1+r, 19 Mor 80



UNCLASSIFIED

THIS REPORT HAS BEEN DELIMITED

AND CLEARED FOR PUBLIC RELEASE

UNDER DOD DIRECTIVE 5200.20 AND

NO RESTRICTIONS ARE IMPOSED UPON

ITS USE AND PISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED.

UNCLASSIFIED

AD____

Reproduced by the


ARMED SERVICES TECHNICAL INFORMATION AGENCY
ARLINGTON HALL STATION
ARLINGTON 12, VIRGINIA



CLASSIFICATION CHANGED TO UNCLASSIFIED FROM CONFIDENTIAL PER AUTHORITY LISTED IN

SEC. OF DEFENSE MEMO. 2 AUG. 60

UNCLASSIFIED



Reproduced by DOCUMENT SERVICE CENTER KNOTT BUILDING, DAYTON, 2, 0 HIO

This document is the property of the United States Government. It is furnished for the duration of the contract and shall be returned when no longer required, or upon recall by ASTIA to the following address: Armed Services Technical Information Agency, Document Service Center, Knott Building, Dayton 2, Ohio.

NOTICE: WHEN GOVERNMENT OR OTHER DRAWINGS, SPECIFICATIONS OR OTHER DATA ARE USED FOR ANY PURPOSE OTHER THAN IN CONNECTION WITH A DEFINITELY RELATED GOVERNMENT PROCUREMENT OPERATION, THE U.S. GOVERNMENT THEREBY INCURS NO RESPONSIBILITY, NOE ANY OBLIGATION WHATSOEVER; AND THE FACT THAT THE GOVERNMENT MAY HAVE FORMULATED, FURNISHED, OR IN ANY WAY SUPPLIED THE SAID DRAWINGS, SPECIFICATIONS, OR OTHER DATA IS NOT TO BE REGARDED BY IMPLICATION OR OTHERWISE AS IN ANY MANNER LICENSING THE HOLDER OR ANY OTHER PERSON OR CORPORATION, OR CONVEYING ANY RIGHTS OR PERMISSION TO MANUFACTURE, USE OR SELL ANY PATENTED INVENTION THAT MAY IN ANY WAY BE RELATED THERETO.





Aberdeen Proving Ground

VULNERABILITY OF DIESEL FUEL

TO

THE 90MM, AP, T33E7 PROJECTILE (U)

THIS DOCUMENT CONSISTS OF PAGES

COPY... 2.0.. OF ... 2.0. COPIES, SERIES.....

D.A. PROJECT NO. - 503-04-004

DEVELOPMENT AND PROOF SERVICES

SEVENTEENTH Report OCO Project No. __TB3-1224B

Regrading data cannot be preciple to mineral EEN PROVING GROUND. MD...415

ABERDEEN PROVING GROUND MARYLAND

REFERENCE COPY JOHN J. BUCK/NOVEMBER 1956

VULNERABILITY OF DIESEL FUEL TO THE 90MM, AP. T33E7 PROJECTILE (U)

SEVENTEENTH REPORT ON

ORDNANCE CORPS PROJECT NO. TB3-1224B

DEPARTMENT OF THE ARMY PROJECT NO. 503-04-004

(AD REPORT 1247)

AUTHORITY

Memo from Director, BRL dtd/10 May 1956

DATES OF TEST

28 August 1956 to 3 October 1956

RETAIN OR DESTROY PER AR 380-5 AND FR345-220 OR COMPARABLE AF OR NAMY REGULATIONS. DO NOT RETURN

21551

THIS DOCUMENT CONSISTS OF PAGES

COPY OF 20 COPIES, SERIES.....

Regrading data cannot be predetermined

Incla to the to 1957 10 del 4-2-

ordeg 0)400.112/298

182

VULNERABILITY OF DIESEL FUEL TO THE 90MM,

AP, T33E7 PROJECTILE (U)

ABSTRACT

OBJECTIVE

The purpose of this test was to determine the ability of the 90mm, AP, T33E7 projectile to ignite diesel fuel stowed in sixteen gallon cans in a tank hull.

SUMMARY

Twelve rounds of 90mm, AP type ammunition were fired through armor plate into cans of diesel fuel. These cans were stowed in the fuel compartments of German Royal Tiger tank hulls to simulate fuel tanks. Sixteen gallon, galvanized steel, powder cans, M2, containing twelve gallons of locally available diesel fuel, were used for this purpose. Diesel fuel temperature was held between 90°F and 100°F for all rounds. The effective target armor thickness varied from 3.44" to 5.05".

CONCLUSIONS

Under the conditions of this test, the 90mm, AP, T33E7 projectile will consistently produce diesel oil fires at **fuel** temperatures of 90°F and above if the target armor and fuel tank are penetrated.

RECOMMENDATIONS

It is recommended that this test be extended to determine the incendiary effectiveness of kinetic energy type projectile when fired into a similar test target containing diesel fuel at temperatures below 80°F.

VULNERABILITY OF DIESEL FUEL TO THE 90MM, AP, T33E7 PROJECTILE (U)

CONTENTS

													PAGE NO.
INTRODUCTION					4					•			3
DESCRIPTION OF MATERIEL	•		•	•	•	•	•	•	•	0	•	•	3
DETAILS OF TEST	•		•	٠	•	•		•		•	•	•	5
PREPARATION	•			•	•	•	•		•	•	•	•	5
WEST PROCEDURE AND RESULTS			•	•	•		•	•	•	•	•	•	6
CONCLUSIONS	•		•	•	•	•			•	•	•	•	n
RECOMMENDATIONS	•	• •	•		•	•		•	•		•	•	11
DISTRIBUTION				•	•	•	•		•	•	•	•	13
APPENDIX A, CORRESPONDENCE										•			A-1

I INTRODUCTION

During the past few years a series of tests has been conducted at Aberdeen Proving Ground to determine the ignitability of diesel fuel in armored tank hulls. In nearly all of these tests, the tank hulls were attacked by HEAT type ammunition of various calibers. It was discovered that diesel fuel at higher temperatures could be ignited under most test conditions. This test was designed to determine the ignitability of armorprotected diesel fuel at higher temperatures when attacked by the 90mm, AP, T33E7 projectile.

II DESCRIPTION OF MATERIEL

A. AMMUNITION:

Projectile - 90mm, AP, T33E7 - Stock Lot Cartridge Case - 90mm, T23B1 - Stock Lot Primer, Percussion, M58 - Stock Lot Propellant - M17, MP - Lot-34492 (.0718" web)

Some 120 oz. of propellant were used to produce a striking velocity of approximately 2750 fps when fired at 100 yards.

B. TARGET

1. Three German Tiger tank hulls were cut in half and the end sections containing the fuel and engine compartments were used as test targets. A general view of one of the test targets, after being fired on, can be seen in Figure 1. The engine and fuel compartments were all made liquid-tight by welding 3/8" mild steel plate over all holes. A false floor of 3/8" mild steel was welded in the engine compartment.



Figure 1 (B19701)

2. The 80mm (3.15") thick armor side plate, at approximately 20° obliquity, was used as the target face. This target face thickness was increased to 4.525" for some rounds by welding a piece of armor plate 16" x 16" x 3/8" to the target face and then welding an additional plate 15" x 15" x 1" to the 3/8 thick armor plate.

3. Galvanized steel powder cans M2 were used as in past tests to simulate diesel fuel tanks. These cans have a maximum capacity of sixteen gallons.

C. FUEL

Locally available diesel fuel, all from the same batch, was used for this test. A sample from this batch of fuel was analyzed and yielded the following results:

Aniline Point - 143°F Flash Point - 138°F

Specific Gravity - .8406 at 78°F

.8476 at 60/60

A.P.I. - 34.5 Diesel Index - 49.3

III DETAILS OF TEST

A. PREPARATION

1. The three tank sections were positioned 100 yards down range from a 90mm, T139 gun mounted on an M48 tank. The tank sections were placed approximately 25 feet apart to eliminate the chances of fire spreading from one hull to another. The horizontal angle of obliquity between axis of the gun bore and the target face (Angle A) was less than 10 degrees. The vertical angle of obliquity between the gun and the target face (Angle B) was greater than 9 degrees and less than 27 degrees. The total angle of obliquity (Angle Θ) was calculated by the following equation:

Cos 9 = Cos A Cos B

- 2. Before each round, the target sections were cleaned. Then an oil-and-grease mix, comprising one part diesel oil, one part SAE 50 oil, and two parts SAE 90 grease, by volume, was painted on all four sides and on the floor of the fuel tank compartment, and on the floor of the engine compartment. These painted surfaces were then sprinkled lightly with locally available sand. This "dirty" condition was maintained on every round of this test for the purpose of simulating a typical diesel engine and fuel compartment.
- 3. For each round the simulated fuel tank was filled three fourths full (twelve gallons) of locally available diesel fuel and positioned inside the fuel compartment of the target section so that the large flat side of the tank was parallel with the target armor. An air space of one inch between the fuel tank and the inside surface of the target armor plate was maintained by inserting several pieces of one inch 0.D. pipe between the fuel tank and the target armor. The fuel tanks were held in position by braces made of steel pipe, aluminum tubing and/or electric conduit.

measured by thermometers and recorded. It was necessary to pre-heat the fuel for several rounds to satisfy the test directive requirement that the fuel type electric heating unit.

4. Before firing each round, the ambient and fuel temperatures were temperature be between 80°F and 100°F. The fuel was heated by a small immersion

B. TEST PROCEDURE AND RESULTS

1. A total of four rounds of 90mm, AP, T33E7, was fired into each of the three tank section targets (two rounds in each side). All rounds were aimed so that the impact would be at a point on the armor plate which corresponded approximately to the geometric center of the enclosed fuel tank. (See Figure 2.)



Figure 2 (B19698)



Figure 3 (B20707)




Figure 4 (B20708)




Figure 5 (B20709)

2. The first six rounds (two at each target hull) were fired into the 80mm (3.15") thick target face (Sponson Box Plate) at approximately 26° obliquity. The tank sections sat level on the ground. The gun elevation or depression was less than one degree. All six of these rounds completely penetrated the 3.15" target armor and fuel tank and damaged the rear of the fuel compartments considerably. The fuel temperatures were between 93°F and 100°F and large fires were produced on all six rounds.

It was then decided to increase the target armor thickness to 4.525" by welding first a piece of three-eighths inch thick armor plate and then a piece of one inch thick armor plate to the original target armor surface. Three rounds (3A, 3B and 3C) were fired into this 4.525" thick composite plate at approximately 25° obliquity. Two of these rounds did not completely penetrate the target and only one small fire was produced. For two of these rounds (3A and 3B) the impact of the projectile produced bulging and cracks on the target armor, but did not produce a complete penetration (Figure 3 and 4). The third round (3C) did penetrate the target armor, but the projectile base was found wedged in the target plate (Figure 5). This round (3C) did produce a small fire in the engine compartment of the target section. The fuel tanks were ruptured by all three of these rounds but mostly at the seams. The ambient temperature (74°F) was lower for these three rounds than for all other rounds.

- 3. To insure complete penetration, it was decided to fire three more rounds into the 4.525" thick composite target armor, reducing the angle of obliquity from approximately 25 degrees to approximately 10 degrees. This reduced obliquity was obtained by elevating the rear of the test target and in effect reduced the effective target armor thickness approximately 0.40 inch.
 - 4. Figure 6 is a summary of round-by-round data and results.

SUMMARY OF 90MM FIRINGS

DATE RD. FIRED NO.		FUEL TEMP (°F)	TARGET PLATE THICK- NESS (T)	ANGLE OF OBLIQ.	THICK- NESS OF PLATE PENE. (T sec 6		RESUL	TS		
28 Aug 1A	83	93	3.15"	26.5°	3.52"	Large fuel			engine	and
28 Aug 13	85	94	3.15"	23.80	3.44"	ft	11	***	ŧŧ	TT
28 Aug 10	87	95	3.15"	24.80	3.47"	11	ir	11	ti	11
29 Aug 2A	. 89	100	3.15"	26.7°	3•53"	tt	11	11	***	11
29 Aug 2B	89	100	3.15"	24.7°	3-47"	11	tt	11	**	***
29 Aug 20	89	100	3.15"	26.7°	3.53"	11	Tit.	**	11	**
11 Sept 3A	. 74	92 *	4.525"	26.4°	5.05"	No fir		did r	ot pene	trate
11 Sept 3B	74	92 *	4.525"	24.00	4.95"	11	111	**	11	ŧ†
11 Sept 30	74	92 *	4.525"	24.3°	4.96"	Small only)	fire	(in	engine	comp.
12 Sept 4A	. 80	100 *	4.525"	10.10	4.60"	Large fuel o			engine	and.
12 Sept 4B	80	100 *	4.525"	9.3°	4.60"	tt	***	**	ti	11
12 Sept 40	80	100 *	4.525"	9.9°	4.61"	11	ff	11	11	11

^{*} Fuel pre-heated

Average striking velocity 2783 fps (est.)

Large fire - Fire that enveloped the largest portion of the tank section with intensely burning fuel.

Small fire - Fire that burned in small area (less than 12 sq. ft.) and did not spread or increase in intensity.

Figure 6




Figure 7 (B19700)




Figure 8 (B19703)



Figure 9 (B20710)

OBSERVATIONS

- 1. The damage to the tank hull sections was quite severe as shown by Figures 7 and 8. Welding and repairs were required after firing two rounds at each section.
- 2. The simulated fuel tanks were severely ruptured on all rounds where the projectile completely penetrated the target armor (see Figure 9).
- 3. At 2780 fps striking velocity, the maximum plate thickness penetrated (between 4.6 and 5.0 ins.) was lower than expected from previous data.

IV CONCLUSIONS

- A. If a 90mm AP projectile has sufficient kinetic energy to penetrate the tank armor protecting the diesel fuel, and the diesel fuel temperature is 90°F or more, a large fire will be produced in areas corresponding to the fuel and engine compartments of the tank.
- B. The 90mm AP T33E7 projectile is as effective or more effective than HEAT type projectiles of similar caliber against diesel fuel stowed in the manner and at the temperatures maintained for these tests.

V RECOMMENDATIONS

A. Firings should be continued to determine the ability of the 90mm AP projectile to ignite diesel fuel at lower temperatures, under similar test conditions.

- B. Vulnerability characteristics (including incendiary effectiveness) of kinetic energy and shaped charge type ammunition should be determined, where necessary, and evaluated by comparison against identical targets.
- C. The target setup designed and used in these firings should be used in future firings of a similar nature with realistic features such as engine grilles incorporated.

SUBMITTED:

JOHN JUBUCK

Ordnance Engineer

REVIEWED:

W. C. PLESS

Chief,

Armor Branch

H. L. ROSENBERG

Chief, Armor and

Ammunition Effectiveness Div.

APPROVED:

TAMIN S. GOODWIN

Assistant Director for

Engineering Testing

Development and Proof Services

	DISTRUBUTION	APG Copy #	of (22) Copies
Copy No.	Name and Address	No.	Copies
3 4 5 6	Chief of Ordnance Washington 25, D. C. ATIN: ORDTA ORDTB ORDTX-AR ORDTT	ARE!	1 1 1
7 8	Commanding General Ordnance Tank Automotive Command Detroit Arsenal Center Line, Michigan ATTN: ORDMC-RM.1 ORDMC-RM.3		1
9	Commanding Officer Watertown Arsenal Watertown, Massachusetts ATTN: Laboratory		1
10	Commanding General Picatinny Arsenal Dover, New Jersey ATTN: Samuel Feltman Amm. Lab.		ı
11-12	Canadian Army Staff 2450 Massachusetts Avenue, N. W. Washington 8, D. C. THRU: OCO, ORDTB		2
13-14	British Joint Services Mission 1800 K Street, N. W Washington 6, D. C. THRU: OCO, ORDTB		2
15	Bureau of Ordnance Department of the Navy Washington 25, D. C.		1
16	Commander Naval Proving Ground Dahlgren, Virginia Ordnance Tank Automotive Command		1
17	1501 Beard Street Detroit 9, Michigan ATIN: ORDMC-FM	•	1

COPY NO.	<u> 1</u>	NO. COPIES
	Ballistic Research Laboratories	
	Aberdeen Proving Ground, Maryland	
18	ATTN: WSL, Tank Vul. Branch	1
19	TBL, Detonation Physics Branch	1
	Armed Services Technical Information Age	ency
	Document Service Center	
	Knott Building	0.0
20	Dayton 2, Ohio	l vellum
	Technical Library Branch	
0	Aberdeen Proving Ground, Maryland	Original
1		1 Reference
2		1 Record

APPENDIX

								PAGE
Α,	CORRESPONDENCE							Δ_7

COPY/sab

OFFICE MEMORANDUM .

APPENDIX A UNITED STATES GOVERNMENT

MrGBeichler/ghm/31240

: Director, Development and Proof Services

DATE: 10 May 1956

FROM : Director, Ballistic Research Laboratories

SUBJECT: Vulnerability of Diesel Fuel to the 90mm T33E7 AP Projectile (Project TB3-1224B)

- 1. It is requested that Development and Proof Services prepare and submit to the Director, BRL, ATTN: Mr. S. Wise, estimates relative to the time and cost to fire an experimental program to determine the vulnerability of armor protected diesel fuel when attacked by the 90mm T33E7 AP projectile. It is preferred that this information be forwarded on Test Program Form ORDBG-TF-997.
- 2. a. Test Conditions: Two conditions are to be considered. The first condition will consist of firing rounds against diesel fuel shielded by three inches of armor at 0° obliquity. If no fires occur, a second condition employing 2 inches of armor (0° obliquity) protection will be conducted. However, if fires occur, the armor shielding the diesel fuel is to be increased to 5 inches at 0° obliquity. The fuel temperature will range between 80°F and 100°F. All rounds are to be dynamically fired at a simulated range of 1000 yards.
- b. Test Procedure: It is recommended that the prototype boxes presently available at D&PS be reconstructed for a more realistic approach to JA III fuel tanks as per discussion of D&PS and BRL representatives. Fourteen gallons of diesel fuel in a sixteen gallon container (powder can) are to be placed flush on the inside of the armor. The wick material used on previous diesel fuel firings will be used in all phases of this test in the areas that wick material might accumulate in tank hulls. All rounds are to enter the fuel containers below the fuel level.
- c. Data to be Collected: Data of primary interest concerns the classification of fires, i.e.:
 - (1) No Fire
 - (2) Ground Fire
 - (3) Small Fire
 - (4) Ordinary Fire
- d. Scope: Five rounds are to be fired at each test set-up. If no fire or all fires occurs the firings are to stop. If mixed conditions results, five additional rounds are to be fired for a ten round sample.

SUBJECT: Vulnerability of Diesel Fuel to the 90mm T33E7 AP Projectile (Project TB3-1224B)

- e. Materials: All material required to conduct these tests is to be provided by D&PS.
- f. Priority and Classification: The DA priority on this program is lA and all results pertaining to the tests are to be classified "CONFIDENTIAL."
- 3. It is anticipated that if costs and time estimates are compatible with resources and plans of the BRL, another memorandum will follow with authority to begin firing.

/s/ H. H. Daubert
H. H. DAUBERT
Lt. Col. Ord Corps
Assistant to Chief
Weapons Systems Laboratory

UNCLASSIFIED

UNCLASSIFIED